

111BRBLF


1-1/4" 17GA P-TRAP, LESS CLEANOUT

Description:

Certification

P-TRAP SHALL BE 1-1/4" GROUND JOINT, 17 GAUGE TUBULAR BRASS, 17 GAUGE 7" WALLBEND, ROUGH BRASS FINISH, BRASS NUTS, LESS FLANGE, LESS CLEANOUT, CERTIFIED BY CSA





Oakville Stamping and Bending Ltd.

2200 Speers Road. Oakville, ON. Canada. L6L 2X8.
T. 905.827.0320 or toll free 1.877.314.6040 F. 905.827.6375 or toll free 1.877.827.6040.