


1-1/4" CAST TRAP WITH CLEANOUT

Description: Certification

P-TRAP SHALL BE 1-1/4" GROUND JOINT, CAST BRASS, 20 GAUGE 7" WALL-BEND, CHROME FINISH, BRASS NUTS, DEEP BELL FLANGE, WITH CLEANOUT, CERTIFIED BY CSA





Oakville Stamping and Bending Ltd.

2200 Speers Road. Oakville, ON. Canada. L6L 2X8. T. 905.827.0320 or toll free 1.877.314.6040 F. 905.827.6375 or toll free 1.877.827.6040.